

Performance Summary Table - 2022

| | |
|------|--|
| i) | No notifications to the Ministry have been required under subsection 8(1). [performance requirements - leak detection and closed systems] |
| ii) | There was no contravention of subsection 11(1). [storage tank floating roof - requirement to float] Subsection 26(1) does not apply to the Site. [primary oil-water separator floating roof - requirement to float] |
| iii) | No orders have been issued to the Site under subsection 52(5) or section 58. [operating parameters and specified source management] |

Performance Summary Table - 2021

| | |
|------|---|
| i) | No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems). |
| ii) | There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float). |
| iii) | No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management). |

Performance Summary Table - 2020

| | |
|------|---|
| i) | No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems). |
| ii) | There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float). |
| iii) | No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management). |

Performance Summary Table - 2019

| | |
|------|---|
| i) | No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems). |
| ii) | There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float). |
| iii) | No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management). |

Performance Summary Table - 2018

| | |
|------|---|
| i) | No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems). |
| ii) | There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float). |
| iii) | No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management). |