

Performance Summary Table - 2024

	Requirement	Summary
i)	Subsection 8(1) Notifications	A notification of a Section 4 contravention (i.e., air emissions from a primary oil water separator not being conveyed to an air pollution control device) was not submitted when it occurred in May 2024, as required by Subsection 8(1). The information required by subsection 8(2) was submitted on November 1, 2024.
ii)	Subsection 11(1) Contraventions	<p>T037 – Tank service switched from C9-200 to RPG</p> <ul style="list-style-type: none"> • Date roof landed – June 20, 2024 @ 8:00 pm • Date roof refloated – June 23, 2024, @ 5:00 am <p>T037 – Tank service switched from RPG to benzene</p> <ul style="list-style-type: none"> • Date roof landed – August 31, 2024 @ 1:00 am • Date roof refloated – September 15, 2024 @ 2:00 am <p>T037 – No change in tank service</p> <ul style="list-style-type: none"> • Date roof landed – November 26, 2024 @ 2:00 pm • Date roof refloated – November 27, 2024 @ 2:00 pm <p>T037 – Tank service switched from benzene to C9-200</p> <ul style="list-style-type: none"> • Date roof landed – December 8, 2024 @ 7:00 pm • Date roof refloated – December 14, 2024 @ 5:00 pm
	Subsection 26(1) Contraventions	Subsection 26(1) does not apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	Subsection 52(5) Orders	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).
	Subsection 58 Orders	No orders have been issued to the Site under section 58 (specified source management).

Performance Summary Table - 2023

	Requirement	Summary
i)	Subsection 8(1) Notifications	A notification of a Section 4 contravention was submitted on January 31, 2023, due to air emissions from a primary oil water separator not being conveyed to an air pollution control device.
ii)	Subsection 11(1) Contraventions	<p>T043 – Tank service switched from C6C9 to RPG</p> <ul style="list-style-type: none"> • Date roof landed – March 3, 2023 @ 8:00 am • Date roof refloated – March 8, 2023 @ 9:20 am <p>T037 – Tank service switched from pygas to light oil</p> <ul style="list-style-type: none"> • Date roof landed – March 6, 2023 @ 8:40 am • Date roof refloated – March 12, @ 6:00 am <p>T037 – Tank service switched from light oil to pygas</p> <ul style="list-style-type: none"> • Date roof landed – June 17, 2023 @ 4:00 am • Date roof refloated – June 23, 2023 @ 8:00 am <p>T043 – Tank service switched from RPG to C6C8</p> <ul style="list-style-type: none"> • Date roof landed – November 15, 2023 @ 12:15 am • Date roof refloated – November 16, 2023 @ 10:37 pm <p>T037 – Tank service switched from pygas to C9-200</p> <ul style="list-style-type: none"> • Date roof landed – November 18, 2023 @ 6:00 am • Date roof refloated – November 22, 2023 @ 2:30 am
	Subsection 26(1) Contraventions	Subsection 26(1) does not apply to the Site (floating roof of primary oil – water separator-requirement to float).
	Subsection 52(5) Orders	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).
iii)	Subsection 58 Orders	No orders have been issued to the Site under section 58 (specified source management).

Performance Summary Table - 2022

i)	No notifications to the Ministry have been required under subsection 8(1). [performance requirements - leak detection and closed systems]
ii)	There was no contravention of subsection 11(1). [storage tank floating roof - requirement to float] Subsection 26(1) does not apply to the Site. [primary oil-water separator floating roof - requirement to float]
iii)	No orders have been issued to the Site under subsection 52(5) or section 58. [operating parameters and specified source management]

Performance Summary Table - 2021

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).

Performance Summary Table - 2020

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).

Performance Summary Table - 2019

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).

Performance Summary Table - 2018

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).