

SDS No.: NOVA-0031A **Revision Date:** 2024.04.04

Version #: 1.0

Product name:

SURPASS® Polyethylene - Not Coloured (All Grades)

SAFETY DATA SHEET

1. Identification of the substance or mixture and of the supplier

Product name: SURPASS® Polyethylene - Not Coloured (All Grades)

Other means of identification

Synonyms, Trade Names: HDPE, LLDPE, MDPE Polyethylene resins, ethylene polymers

SDS number: NOVA-0031A

Recommended use of the chemical and restrictions on use

Recommended use: Thermoplastic resin extruded into film, sheet or moulded into containers and other

shapes.

Restrictions on use: All uses other than the identified.

Manufacturer/Importer/Supplier/Distributor Information

Manufacturer

Company Name: NOVA Chemicals

Address: P.O. Box 2518, Station M

Calgary, Alberta T2P 5C6

Telephone: Product Information: 1-412-490-4063

SDS Information Email: msdsemail@novachem.com

Supplier

Company Name: NOVA Chemicals International (SA)

Address: Avenue de la Gare 14

1700 Fribourg

Telephone: +41-26-426-5757

SDS Information Email: msdsemail@novachem.com

Emergency telephone number:

+1-800-561-6682, +1-403-314-8767 (NOVA Chemicals) (24 hours)

Asia Pacific: +65 3158 1074 (NCEC) (24 hours)

2. Hazard(s) identification

GHS classification

Not classified

Label elements

Pictogram: No symbol

Signal Word: No signal word.

Hazard Statement: not applicable

Precautionary Statements

Prevention: Keep away from heat, hot surfaces, sparks, open flames and other

ignition sources. No smoking. Ground and bond container and receiving equipment. Use explosion-proof [electrical/ventilating/lighting] equipment. Wash hands thoroughly after handling. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Wear protective gloves/ protective clothing/ eye protection/ face protection. [In case of

SDS_TW 1/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

inadequate ventilation] wear respiratory protection.

Response: IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Get medical

advice/attention. IF ON SKIN: Wash with plenty of water/soap. If skin irritation occurs: Get medical advice/attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses,

if present and easy to do. Continue rinsing.

Storage: Store in accordance with local/regional/national regulations. Protect from

sunlight.

Disposal: Dispose of contents/container in accordance with

local/regional/national/international regulations. Refer to manufacturer or

supplier for information on recovery or recycling.

Other hazards which do not result in GHS

not result in GHS classification:

If small particles are generated during further processing, handling or by other means, may form combustible dust concentrations in air. Spilled

product may create a dangerous slipping hazard.

3. Composition/information on ingredients

Mixtures

Composition Comments: No hazardous ingredients.

4. First-aid measures

Description of first aid measures

Inhalation: IF INHALED: Remove person to fresh air and keep comfortable for breathing. Get

medical advice/attention.

Skin Contact: IF ON SKIN: Wash with plenty of water/soap. If skin irritation occurs: Get medical

advice/attention.

Eye contact: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact

lenses, if present and easy to do. Continue rinsing. Get medical advice/attention.

Ingestion: IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Get medical

advice/attention.

Most important symptoms and effects, both acute and delayed

Symptoms: Thermal burns. Respiratory irritation. Mechanical irritation.

Personal Protection for First-aid Responders:

No data available.

Indication of immediate medical attention and special treatment needed

Treatment: After adequate first aid, no further treatment is required unless symptoms

reappear. Burns should be treated as thermal burns. Molten resin will come off as healing occurs; therefore, immediate removal from the skin is not necessary. Treatment should be directed at the control of symptoms and the clinical condition

of the patient. No adverse effects due to ingestion are expected.

5. Fire-fighting measures

General Fire Hazards: Polyethylene is a noncombustible solid, but dusts may form explosive

mixtures in air. Product will burn at high temperatures but is not considered flammable. Under fire conditions, product will readily burn and emit irritating

SDS_TW 2/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

smoke.

Suitable (and unsuitable) extinguishing media

Suitable extinguishing media:

Water fog or water spray. Small fires: Dry chemical, carbon dioxide (CO2) or

foam.

Unsuitable extinguishing

media:

Avoid water in straight hose stream; will scatter and spread fire.

Special hazards arising from the substance or mixture:

Upon heating, polyethylene may emit various oligomers, waxes and oxygenated hydrocarbons as well as carbon dioxide, carbon monoxide and small amounts of other organic vapours (e.g. aldehydes, acrolein). Inhalation of these decomposition products may be hazardous. Powdered material may form explosive dust-air mixtures. Risk of dust-air explosion is increased if flammable vapours are also present. Static discharge: material can accumulate static charges which may cause an incendiary electrical discharge.

Special protective equipment and precautions for fire-fighters

Special fire-fighting procedures:

Keep upwind. Keep unauthorised personnel away. Move containers from fire area if you can do so without risk. Fight fire from maximum distance or use unmanned holders or monitor nozzles. Apply extinguishing media carefully to avoid creating airborne dust. Fine dust dispersed in air in sufficient concentrations, and in the presence of an ignition source is a potential dust explosion hazard. Water may be used to flood the area. Use water spray to cool fire exposed surfaces and to protect personnel. Avoid inhaling any smoke and combustion materials. Remove and isolate contaminated clothing and shoes. Prevent run-off from fire control or dilution from entering streams, sewers or drinking water supply.

Special protective equipment for fire-fighters:

Wear positive pressure self-contained breathing apparatus (SCBA).

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures:

Isolate area. Alert stand-by emergency and fire-fighting personnel. Wear appropriate personal protective equipment. For additional information, refer to Section 8.

Methods and material for containment and cleaning up:

Avoid standing or walking on spilled product. Spilled product may create a dangerous slipping hazard. In case of leakage, eliminate all ignition sources. Stop leak if safe to do so. Dust deposits should not be allowed to accumulate on surfaces, as these may form an explosive mixture if they are released into the atmosphere in sufficient concentration. Avoid dispersal of dust in the air (i.e., clearing dust surfaces with compressed air). Use appropriate tools to put the spilled solid in an appropriate disposal or recovery container. Use non-sparking tools. Recover and reclaim or recycle, if practical.

Environmental precautions:

Prevent entry into waterways, sewer, basements or confined areas.

7. Handling and storage

Handling

Safe handling advice:

Keep away from uncontrolled heat and incompatible materials. Wash hands thoroughly after handling. Minimise dust generation and accumulation.

SDS_TW 3/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

Routine housekeeping should be instituted to ensure that dusts do not accumulate on surfaces. Dry powders can build static electricity charges when subjected to the friction of transfer and mixing operations. Provide adequate precautions, such as electrical grounding and bonding, or inert atmospheres. Ground all material handling and transfer equipment. For additional information on control of static and minimizing potential dust and fire hazards, refer to NFPA-654, "Standard for the Prevention of Fire and Dust Explosions from the Manufacturing, Processing and Handling of Combustible Particulate Solids", current edition. Use in a well-ventilated area. Wear eye protection/protective gloves as needed/wear full face-shield during thermal processing if contact with molten material is possible/wear respirator if dusty. Spilled product may create a dangerous slipping hazard. Avoid release to the environment.

Storage Safe storage conditions:

Store in accordance with all current regulations and standards. Storage area should be clearly identified, well-illuminated and clear of obstruction. Store in closed, grounded and properly designed vessels. Keep away from uncontrolled heat and incompatible materials. Protect from sunlight. Outdoor storage of product in bags requires protection from ultra-violet sunlight by use of a UV stabilized bag or alternate means. Avoid accumulation of dust by frequent cleaning and suitable construction of storage and handling areas. Keep shovels and vacuum systems readily available for cleanup of loose material. DO NOT enter filled bulk containers and attempt to walk over product, due to risk of slipping and possible suffocation. Use a fall arrest system when working near open bulk containers.

8. Exposure controls/personal protection

Control parameters

Occupational Exposure Limits

During dusty conditions ACGIH recommends for Particles (insoluble or poorly soluble) not otherwise specified a TWA of 10 mg/m3 (inhalable particles), 3 mg/m3 TWA (respirable particles).

Biological Limit Values

No biological exposure limits noted for the ingredient(s).

Engineering measures:

Engineering methods to reduce hazardous exposure are preferred controls. Methods include mechanical ventilation (dilution and local exhaust) process or personal enclosure, remote and automated operation, control of process conditions, leak detection and repair systems, and other process modifications. Ensure that dust-handling systems (such as exhaust ducts, dust collectors, vessels, and processing equipment) are designed in a manner to prevent the escape of dust into the work area (i.e., there is no leakage from the equipment). Ensure all exhaust ventilation systems are discharged to outdoors, away from air intakes and ignition sources. Supply sufficient replacement air to make up for air removed by exhaust systems. Administrative (procedure) controls and use of personal protective equipment may also be required. It is recommended that all dust control equipment such as local exhaust ventilation and material transport systems involved in handling of this product contain explosion relief vents or an explosion suppression system or an oxygen-deficient environment. Use only appropriately classified electrical equipment and powered industrial trucks.

Individual protection measures, such as personal protective equipment

Eye/face protection: Safety glasses. Wear a face shield when working with molten material.

Hand Protection: Material: Wear gloves to protect against thermal burns.

SDS_TW 4/10



Protection:

Product name:

SURPASS® Polyethylene - Not Coloured (All Grades)

Skin and Body Wear appropriate clothing to prevent any possibility of skin contact. Wear

work clothes with long sleeves and pants. Safety footwear with good traction is recommended to help prevent slipping. Static Dissipative (SD) rated

SDS No.: NOVA-0031A

Revision Date: 2024.04.04

footwear is also recommended.

Respiratory Protection: Appropriate NIOSH approved air-purifying respirator or self-contained

breathing apparatus should be used. Supplied air breathing apparatus must be used when oxygen concentrations are low or if airborne concentrations

exceed the limits of the air-purifying respirators.

Hygiene measures: Use effective control measures and PPE to maintain worker exposure to

concentrations that are below these limits. Ensure that eyewash stations

and safety showers are in close proximity to work locations.

9. Physical and chemical properties

Information on basic physical and chemical properties

Appearance

Physical state: solid

Form: Pellets or Granular powder

Colour: white / colourless / translucent

Odour: Minimal, Mild
Odour Threshold: No data available.

Melting Point: 105 - 135 °C (221 - 275 °F) (Melting Point) 85 - 127 °C (185 -

261 °F) (Softening point)

Boiling Point: not applicable

Flammability: May form combustible dust concentrations in air [if small

particles are generated during further processing, handling or

by other means.]

Upper/lower limit on flammability or explosive limits

Explosive limit - upper:

Explosive limit - lower:

Flash Point:

Self-ignition:

Decomposition Temperature:

ph:

not applicable

not applicable

No data available.

> 300 °C (> 572 °F)

not applicable

. Viscosity

Dynamic viscosity:No data available.Kinematic viscosity:not applicableFlow Time:No data available.

Solubility(ies)

Solubility in Water: Insoluble in water Solubility (other): No data available. not applicable Partition coefficient (n-octanol/water): Vapour pressure: not applicable Relative density: 0.905 - 0.970Density: 905 - 970 kg/m3 **Bulk density:** No data available. Vapour density (air=1): not applicable

Particle characteristics

Particle Size: 0.1 - 5 MM

SDS_TW 5/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

10. Stability and reactivity

Reactivity: Contact with incompatible materials. Sources of ignition. Exposure to

heat.

Chemical stability: Material is stable under normal conditions.

Possibility of hazardous

reactions:

Hazardous polymerization not likely to occur.

Conditions to avoid: Avoid exposing to extended periods of heat and contact with strong

oxidizing substances.

Incompatible Materials: Strong oxidising agents. Organic solvents, ether, gasoline, lubricating

oils, chlorinated hydrocarbons and aromatic hydrocarbons may react with and degrade polyethylene. Powdered material may form explosive dust-air mixtures. Risk of dust-air explosion is increased if

flammable vapours are also present.

Hazardous

decomposition products:

Upon decomposition, polyethylene may emit various oligomers, waxes and oxygenated hydrocarbons as well as carbon dioxide, carbon monoxide and small amounts of other organic vapours (e.g. aldehydes, acrolein). Inhalation of these decomposition products may

be hazardous.

11. Toxicological information

Information on toxicological effects

Inhalation: During processing, thermal fumes and inhalation of fine particles may

cause respiratory irritation.

Skin Contact: During processing, contact with powder or fines may cause mechanical

irritation. Molten material will produce thermal burns.

Eye contact: During processing, contact with powder or fines may cause mechanical

irritation. Molten material will produce thermal burns.

Ingestion: Ingestion of this product is not a likely route of exposure.

Symptoms related to the physical, chemical and toxicological characteristics

Inhalation: Respiratory irritation.

Skin Contact: Mechanical irritation. Thermal burns. Negligible irritation of the skin based

on chemical structure (polymer).

Eye contact: Mechanical irritation. Thermal burns. May cause mild, short-lasting

discomfort to eyes.

Ingestion: No adverse effects due to ingestion are expected.

Information on likely routes of exposure

Acute toxicity (list all possible routes of exposure)

Oral

Product: LD 50: > 5,000 mg/kg (estimated)

Dermal

Product: Not classified for acute toxicity based on available data.

SDS_TW 6/10



SDS No.: NOVA-0031A **Revision Date: 2024.04.04**

Product name:

SURPASS® Polyethylene - Not Coloured (All Grades)

Inhalation

Product: Not classified for acute toxicity based on available data.

Repeated dose toxicity

Product: No data available.

Skin Corrosion/Irritation

Product: No data available.

Serious Eye Damage/Eye Irritation

Product: No data available.

Respiratory or Skin Sensitisation

Product: No data available.

Carcinogenicity

Not classified **Product:**

Germ Cell Mutagenicity

In vitro

Product: There are no known or reported genetic effects.;

In vivo

Product: There are no known or reported genetic effects.

Reproductive toxicity

Product: There are no known or reported reproductive effects.

Specific Target Organ Toxicity - Single Exposure

No data available. Product:

Specific Target Organ Toxicity - Repeated Exposure

No data available. Product:

Aspiration Hazard

Product: Not classified.

Information on health hazards

Other hazards

No data available. **Product:**

12. Ecological information

General information: SURPASS® resins are expected to be inert in the environment. They float

on water and are not biodegradable. They are not expected to

bioconcentrate (accumulate in the food chain) due to their high molecular weight. SURPASS® pellets are not expected to be toxic if ingested but may

represent a choking hazard if ingested by waterfowl or aquatic life.

Ecotoxicity:

Acute hazards to the aquatic environment:

Fish

Product: LC 50 (96 h): > 100 mg/l

Aquatic Invertebrates

Product: EC 50 (Daphnia magna, 48 h): > 100 mg/l

Toxicity to aquatic plants

Product: EC 50 (72 h): > 100 mg/l

SDS TW 7/10



SURPASS® Polyethylene - Not Coloured (All Grades)

Chronic hazards to the aquatic environment:

Fish

Product: NOEC : > 100 mg/l

Aquatic Invertebrates

Product: NOEC : > 100 mg/l

Toxicity to aquatic plants

Product: NOEC : > 100 mg/l

Persistence and degradability

Biodegradation

Product: Not readily degradable. Under optimal oxidation conditions, >99% of

polyethylene will remain intact after exposure to microbial actions. Product will slowly change (embrittle) in the presence of sunlight, but will not fully breakdown. Product buried in landfill has been found to be stable over time. No toxic degradation products are known to be produced.

SDS No.: NOVA-0031A

Revision Date: 2024.04.04

BOD/COD Ratio

Product: No data available.

Bioaccumulative potential

Bioconcentration Factor (BCF)

Product: Polyethylene resins may accumulate in the digestive systems of birds

and aquatic life, causing injury and possible death due to starvation.

Partition Coefficient n-octanol / water (log Kow)

Product: Log Kow: not applicable

Mobility in soil:

Product Biologically persistent. This product has not been found to migrate

through soils.

Other adverse effects:

Other hazards

Product: Polyethylene resins are persistent in aquatic and terrestrial systems.

13. Disposal considerations

Disposal methods: Dispose of contents/container to an appropriate treatment and disposal

facility in accordance with applicable laws and regulations, and product characteristics at time of disposal. Preferred disposal methods for polyethylene in order of preference are: 1) clean and reuse if possible, 2) recover and resell through plastic recyclers or resin brokers, 3) incinerate

with waste heat recovery and 4) landfill. DO NOT ATTEMPT TO

DISPOSE OF BY UNCONTROLLED INCINERATION. Open burning of

plastics at landfills should not be undertaken.

Contaminated

Packaging:

Check regional, national and local environmental regulations prior to

disposal.

14. Transport information

IATA

Not Regulated.

IMDG

Not Regulated.

SDS_TW 8/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

15. Regulatory information

Ongoing occupational hygiene, medical surveillance programs, site emission or spill reporting may be required by federal, state, provincial or local regulations. Check for applicable regulations.

Please contact your NOVA Chemicals representative for additional information.

16. Other information

Issue Date: 2024.04.04

Version #: 1.0

Organization that prepared the SDS and SDS Author:

SDS Author: STEWARDP@novachem.com

Further Information:

Exposure to the Hazardous Combustion and Decomposition Products as described in the SDS, Sections 5 and 10, may be linked with various acute and chronic health effects. These effects include irritation of eyes and upper respiratory tract primarily from the aldehydes, breathing difficulties, systemic toxicity such as liver, kidney, and central nervous system effects.

NOVA Chemicals has monitored worker exposures to emissions during commercial-scale processing of polyethylene. Concentrations of hazardous decomposition products were determined to be well below established exposure limits in the workplace. "Quantitation of Employee Exposure to Emission Products Generated By Commercial-Scale Processing of Polyethylene" is available in the Am. Ind. Hyg. Assoc. J. 56:809-814 (1995) and "Quantification of Emission Compounds Generated During Commercial-Scale Processing of Advanced SCLAIRTECH™ Polyethylene" is available in the Journal of Plastic Film & Sheeting Volume 26 Issue 2, April 2010.

For information on ventilation considerations for the control of volatile air contaminants from polyethylene, please request a copy of NOVA Chemicals' publication, "Ventilation Guidelines for Heat-Processing Polyethylene Resins".

For additional information on unloading hopper cars containing plastic resins, refer to NOVA Chemicals' publication, "Hopper Car Unloading Guide".

For information on processing properties and selection of SURPASS resin grades, refer to the SURPASS Product Data Sheets available on our web site, under Products & Applications: http://www.novachemicals.com.

For additional information on preventing polyethylene resin loss, refer to published plastic industry publications and resources under Operation Clean Sweep® product stewardship program; now downloadable from the web at http://www.opcleansweep.org/.

Polyethylene fines and dust particles are listed as a Class I combustible dust by the National Fire Protection Association (see NFPA-68, Table F.1 (e)). For additional information on control of static and minimizing potential dust and fire hazards, refer to NFPA-654, "Standard for the Prevention of Fire and Dust Explosions from the Manufacturing, Processing and Handling of Combustible Particulate Solids", current

SDS_TW 9/10



SURPASS® Polyethylene - Not Coloured (All Grades)

SDS No.: NOVA-0031A Revision Date: 2024.04.04

edition.

Explosivity testing was done on one SURPASS® resin with Pmax = 5.2 bar, Kst = 13 (bar m/s) and Minimum Ignition Energy (MIE) = 1000-10,000; dust explosion class = St 1; this data was obtained for polyethylene with a final particle size of 100% <250 um and moisture content between 0 and 0.2%. Similar results are expected for the remaining SURPASS® polyethylene resin grades.

For SURPASS resin grade specific information including food contact compliance statements, please contact your sales representative or refer to NOVA Chemicals' polyethylene Product Data Sheets.

References: Available on request.

Revision Information Not relevant.

Disclaimer: ALTHOUGH THE INFORMATION CONTAINED IN THIS DOCUMENT IS PRESENTED IN

GOOD FAITH, BASED ON AVAILABLE INFORMATION BELIEVED TO BE RELIABLE AT THE TIME OF PREPARATION OF THIS DOCUMENT, NOVA CHEMICALS MAKES NO WARRANTIES OR REPRESENTATIONS WITH RESPECT TO THE INFORMATION OR THE PRODUCT/MATERIALS DESCRIBED HEREIN, AND EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES AND CONDITIONS (INCLUDING ALL WARRANTIES AND CONDITIONS OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE).

NO FREEDOM FROM INFRINGEMENT OF ANY PATENT OWNED BY NOVA CHEMICALS OR OTHERS IS TO BE INFERRED. THIS INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. PLEASE CONTACT NOVA CHEMICALS FOR THE MOST

CURRENT VERSION OF THIS SDS. NOVA CHEMICALS DOES NOT ASSUME RESPONSIBILITY FOR SDS OBTAINED FROM THIRD PARTY SOURCES.

UNLESS SPECIFICALLY AGREED OTHERWISE, NOVA CHEMICALS DOES NOT TAKE RESPONSIBILITY FOR USE, TRANSPORTATION, STORAGE, HANDLING OR

DISPOSAL OF THE PRODUCT/MATERIALS DESCRIBED HEREIN.

NOVA Chemicals®

is a registered trademark of NOVA Brands Ltd.; authorized use/utilisation autorisée.

Advanced SCLAIRTECH™ is a trademark of NOVA Chemicals.

Operation Clean Sweep® is a registered service mark of Plastics Industry Association, Inc.

SURPASS® is a registered trademark of NOVA Chemicals Corporation in Canada and of NOVA Chemicals (International) S.A. elsewhere; authorized use/utilisation autorisée.

SDS_TW 10/10