

Performance Summary Table - 2018

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).

Performance Summary Table - 2019

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).

Performance Summary Table - 2020

i)	No notifications have been required to be given to the Ministry as per subsection 8(1) (performance requirements re: leak detection and closed systems).
ii)	There was no contravention of subsection 11(1) (storage tank floating roof- requirement to float). Subsection 26(1) does not currently apply to the Site (floating roof of primary oil – water separator-requirement to float).
iii)	No orders have been issued to the Site under subsection 52(5) (Operating Parameters) or section 58 (specified source management).